

MANUFACTURING FOR FACE GEARS

ABSTRACT OF THE DISCLOSURE

5

10 Enveloping worm face gears are machined with plunge feeding. Machining could
be done by hobbing or cold rolling. This reduces production cost and makes
manufacturing easier.